


HONEYWELL PART NUMBER
136PC05G2







GENER

PRESSURE
OVERPRESS
TEMPERATU
STORAGE
OPERATE
COMPENS
SUPPLY VO
INPUT RES

ELECTRICAL PE

NULL OFF
F.S.O.
LINEARIT
INPUT
INPUT
HYSTERES

TEMPERATURE E

NULL SHI
SENSITIV

NOTES
1 - TERMINALS ARE PL
2 - LIMIT SOLDERING
3 F.S.O. IS THE AL
END POINTS (NULL
4 - INPUT MEDIA LIMI
ATTACK POLYESTER

DESIGN UNITS: MM
TOLERANCES UNLESS NOTED:

NO PLACES	X	±
ONE PLACE	.X	±
TWO PLACE	.XX	±
THREE PLACE	.XXX	±
ANGLES	X	±

THIRD ANGLE PROJ

Downloaded from Arrow.com.